SPINNY

Spinny Car Report (Product ID: 113472)

2015 Maruti Suzuki Ciaz

ZXI+

Rs 5,85,000

58859 KM | petrol | manual | grey | Saket, Delhi

Registration Year: May 2015
RTO: South West Delhi

Make Year: Apr 2015
Owners: 1

Insurance: Comprehensive (May. 2020)
Reason for sale: Other Reason

LEFT FRONT CORNER VIEW

LEFT SIDE VIEW

LEFT REAR CORNER VIEW

BACK VIEW

FRONT VIEW

ENGINE & BONNET OPEN FRONT VIEW

CLUSTERMETER VIEW

DASHBOARD VIEW

Introducing Spinny Assured

Our Promise of Complete Happiness & Satisfaction
with Every Spinny Assured Car

SPINNY ASSURED

5 Days	200 PTS	1 Year
Money Back Gurantee	Quality Inspection Check	Service Warranty

Car inspection report

Exterior

- There is dent on Right running board,Front right door,Rear right door,Roof and Boot/Dicky door
- There is scratch on Front right door,Rear right door,Roof and Boot/Dicky door
- Front Bumper,Bonnet,Rear Bumper and Left running board are repaired
- Bonnet have corrosion
- No body parts have been replaced
- No body parts have cracks
- Front Bumper,Bonnet,Front Right Fender,Rear right door,Right Quarter panel,Rear Bumper,Left Quarter panel,Left running board,Rear left door,Left Front Door and Left fender are Repainted
- No cracks in rims and alloys
- No dents in rims and alloys
- No repair in pillars
- Turn signal lights working fine

Engine Compartment

- Car has no white or black smoke
- Engine has no abnormal noise
- Engine has no back compression
- Radiator is in good condition
- Coolant is free of foreign material
- Ignition system is working fine
- Engine starting in single crank
- Battery is in good condition
- Steering system working properly
- Alternator belt is working smoothly
- Wiper working smoothly
- AC compressor is working smoothly

Road Test

- Steering is perfectly aligned
- Power steering operates as designed
- Engine exhibits appropriate power
- Gear shift is operating smoothly

Underbody

- Main oil seal has no sign of oil leaks

Interiors

- Central locking system is working fine
- Upholstery is in good condition
- Roof lining is in good condition
- Carpet and floor mats are free of cuts and tears
- All functions in cluster panel are working fine
- AC blower operates as designed

Tyres

Right Front Tyre	60.0%
Left Front Tyre	60.0%
Right Rear Tyre	80.0%
Left Rear Tyre	80.0%
Spare Tyre	70.0%

Pricing

Spinny Price	Market Price	New Car on-road Price
Rs 5,85,000	Rs 6,48,220	Rs 10,50,000
Including benefits of Spinny Assured	Save Rs. 63,220 with Spinny	Save 44.3% with Spinny

For more details visit
www.spinny.com

For test drive visit us at
(It is advisable to check availability online)

You can call us on
7277277275



View this product on www.spinny.com >