# 2014 Hyundai Grand i10

**Asta 1.1 CRDi**

**Rs 4,42,000**

61940 KM | diesel | manual | white | BTM Layout, Bangalore

Registration Year: Jun 2014
RTO: Bangalore

Make Year: Jun 2014
Owners: 1

Insurance: Uninsured (. None)
Reason for sale: None

LEFT FRONT CORNER VIEW


LEFT SIDE VIEW

LEFT REAR CORNER VIEW

BACK VIEW

FRONT VIEW

ENGINE & BONNET OPEN FRONT VIEW

CLUSTERMETER VIEW

DASHBOARD VIEW

## Introducing Spinny Assured

Our Promise of Complete Happiness & Satisfaction with Every Spinny Assured Car

SPINNY ASSURED

| 5 Days | 200 PTS | 1 Year |
|---|---|---|
| Money Back Gurantee | Quality Inspection Check | Service Warranty |

## Car inspection report

### Exterior

- There is dent on Bonnet,Front Right Fender and Right running board
- There is scratch on Bonnet,Front Right Fender,Front right door,Left Quarter panel,Rear left door and Left Front Door
- No body parts have been repaired
- No corrosion in body panels
- No body parts have been replaced
- No body parts have cracks
- Front Bumper,Bonnet,Right running board,Rear right door,Right Quarter panel,Rear Bumper,Left Quarter panel,Left running board,Rear left door,Left Front Door and Left fender are Repainted
- No cracks in rims and alloys
- No dents in rims and alloys
- No repair in pillars
- Turn signal lights working fine

### Underbody

- Main oil seal has no sign of oil leaks

### Interiors

- Central locking system is working fine
- Upholstery is in good condition
- Roof lining is in good condition
- Carpet and floor mats are free of cuts and tears
- All functions in cluster panel are working fine
- AC blower operates as designed

### Tyres

| | |
|---|---|
| Right Front Tyre | 60.0% |
| Left Front Tyre | 60.0% |
| Right Rear Tyre | 60.0% |
| Left Rear Tyre | 100.0% |
| Spare Tyre | 60.0% |

### Engine Compartment

- Car has no white or black smoke
- Engine has no abnormal noise
- Engine has no back compression
- Radiator is in good condition
- Coolant is free of foreign material
- Engine starting in single crank
- Battery is in good condition
- Steering system working properly
- Alternator belt is working smoothly
- Wiper working smoothly
- AC compressor is working smoothly

### Road Test

- Steering is perfectly aligned
- Engine exhibits appropriate power
- Gear shift is operating smoothly

## Pricing

| Spinny Price | Market Price | New Car on-road Price |
|---|---|---|
| Rs 4,42,000 | Rs 4,94,250 | Rs 8,20,000 |
| Including benefits of Spinny Assured | Save Rs. 52,250 with Spinny | Save 46.1% with Spinny |

For more details visit
www.spinny.com

For test drive visit us at
(It is advisable to check availability online)

You can call us on
7277277275